

ADMINISTRATIVE RECORD INDEX
UPDATE 16
ALSCO ANACONDA SITE
GNADENHUTTEN, OHIO

FICHE/FRAME	PAGES	DATE	TITLE	AUTHOR	RECIPIENT	DOCUMENT TYPE	DOCNUMBER
35	90/02/16		Final Revised Community Relations Plan	Jacobs Engineering Group, Inc.	USEPA	Reports/Studies	1
26	90/04/12		Statement of Work Supplemental RI/FS Activities	ERM-Southwest, Inc.	USEPA	Reports/Studies	2
260	90/08/20		Remedial Design/ Remedial Action (RD/RA) Work Plan	ERM-Southwest, Inc.	USEPA	Reports/Studies	3
42	90/11/01		Health and Safety Plan Ground Water Operable Unit Supplemental Remedial Investigation/ Feasibility Study	ERM-Southwest, Inc.	USEPA	Reports/Studies	4
74	90/11/08		Field Sampling Plan Ground Water Operable Unit Supplemental RI/FS	ERM-Southwest, Inc.	USEPA	Reports/Studies	5
83	90/11/08		Work Plan - Ground Water Operable Unit Supplemental Remedial Investigation/Feasibility Study	ERM-Southwest, Inc.	USEPA	Reports/Studies	6
412	90/11/26		Quality Assurance Project Plan, Ground Water Operable Unit Supplemental RI/FS	ERM-Southwest, Inc.	USEPA	Reports/Studies	7
330	90/11/29		Interim Report, Waste Classification, Treatment and Disposal Source Material Operable Unit Wastes	ERM-Southwest, Inc.	USEPA	Reports/Studies	8
35	90/12/21		Work Plan for Investigative Trenching and Waste Characterization	ERM-Southwest, Inc.	USEPA	Reports/Studies	9
35	91/01/22		Health and Safety Plan Source Material Operable Unit	ERM-Southwest, Inc.	USEPA	Reports/Studies	10

00004915

Page No. 2
05/31/91

ADMINISTRATIVE RECORD INDEX

UPDATE #6

ALSCO ANACONDA SITE
GNADENHUTTEN, OHIO

FICHE/FRAME	PAGES	DATE	TITLE	AUTHOR	RECIPIENT	DOCUMENT TYPE	DOCNUMBER
			Investigative Trenching and Waste Characterization				

ACRONYM GUIDE for the Administrative Record
Alco Anaconda Site, Update #5
Gnadenhuetten, Ohio

ACRONYM	DEFINITION
RD/RA	Remedial Design/ Remedial Action
RI/FS	Remedial Investigation/ Feasibility Study
USEPA	United States Environmental Protection Agency